

Exhibit 23

[CERTIFIED TRANSLATION]

[round logo:
GOVERNMENT OF
PUERTO RICO]

GOVERNMENT OF PUERTO RICO
Department of Public Safety
Puerto Rico Police Bureau

Alexis Torres Ríos
Designated Secretary

Antonio López Figueroa
Designated Commissioner

SAIC-NILIAF-DDARC-10-11
March 8, 2021

Officer Geovan Ortiz De Jesus 35203
Investigator
Force Investigation Unit

[illegible signature]
Sergeant Mario Reyes Mulero 8-11004
Director
Service and Private Weapons Deposit Division

[illegible signature] [hw: 7370]
Officer José L. Sánchez Diaz 7370
Armorer, P.R. Police Bureau
Service and Private Weapons Deposit Division

[round ink stamp:
PUERTO RICO POLICE
OFFICIAL STAMP]

SERVICE WEAPON INSPECTION

This is in reference to document SARP-NIA-DIIUF-AH-2-023 dated March 9, 2021, signed by Officer Geovan Ortiz De Jesus 35203, investigator, Force Investigation Unit. Officer Ortiz De Jesús requested an inspection of the service weapon assigned to **Officer Elvis R. Green Berrios 33640**, a member of the Bayamón Area Motorized Unit, in connection with an incident of critical discharge, which occurred on January 6, 2021, according to Police Report No. 2021-13-010-000060.

DESCRIPTION OF [WEAPON] ANALYZED

Type – Gun
Brand – Sig Sauer
Model – P320
Caliber - .9 mm
Serial No. – 58H014298
Property No. – 168831

✉ P.O. Box 70166 · San Juan, Puerto Rico 00936-8166 ☎ 787.793.1234 📠 787.781.0080


Tips ☎ 787.343.2020 🌐 www.dsp.pr.gov

[round logo:
PUERTO RICO
DEPARTMENT OF
PUBLIC SAFETY]

[logo:
PUERTO RICO
POLICE BUREAU
PROTECTION
INTEGRITY]

Attachment [hw: 11]

I hereby certify that this is a true and accurate
translation to the best of my abilities.


Miriam R. Garcia
Federally Certified Court Interpreter
Certificate No. 03-051

[CERTIFIED TRANSLATION]

[round logo: GOVERNMENT OF
GOVERNMENT OF
PUERTO RICO] GOVERNMENT OF PUERTO RICO
Department of Public Safety
Bureau of the Puerto Rico Firefighters Corps [sic]

Page 2 of 2

SECURITY MECHANISMS

- Takedown Safety Lever
- Disconnecter
- Striker Safety
- Secondary Striker Notch

INSPECTION PERFORMED

- Internal mechanisms (slide assembly and receiver/grip assembly)
- External mechanism (operation/sets)

TESTS PERFORMED

- Firing mechanism
- Trigger group
- The weapon was loaded and its safety mechanisms were left vulnerable and it did not fire.
- The operation of its internal and external mechanisms was inspected and no defects were found.
- Firing tests were performed and no defects were found.
- It was dropped from a height of approximately (5') feet and its firing mechanism was not engaged.

[round ink stamp:
PUERTO RICO POLICE
OFFICIAL STAMP]

FINDINGS


- No evidence was found of any defects in the service weapon.
- It was found that the service weapon needs maintenance.

RESULTS OF ANALYSIS

After the inspection and tests were performed on the weapon in question, **no evidence was found** of any defects that would cause its malfunction and the weapon is in good condition.

For the corresponding investigation procedures. |

Attachment [hw: 11]
[illegible] [hw: 2-2]

I hereby certify that this is a true and accurate
translation to the best of my abilities.

Miriam R. Garcia
Federally Certified Court Interpreter
Certificate No. 03-051